



[www.BeSoji.com](http://www.BeSoji.com)



PRE-PURCHASE  
**YELLOW BOOK**

---

BESOJI FZ-LLC

+971 56 817 8171

IN5 TECH, MEDIA CITY

HELLO@BESOJI.COM



## Type Of Inspection

Pre-Delivery Inspection

## Date

Wednesday, June 26, 2024

## Time

11:00 AM

## Vehicle Details

### Make

TOYOTA

### Model

Land cruiser

### Year

2024

### Engine Size

6-Cylinder

### Mileage (KM)

6

### Fuel Type

Diesel

### Regional Specs

GCC

### Transmission

Automatic

### Interior

Leather

### VIN Number

12345678901234567

### Number of Keys

2

### Spare Tire

Available

## Vehicle Summary

We've explained **some** of the faults below.  
**Please refer to the full report for all the faults.**

### Inspector Comments

The brake pedal feels a little spongy while stationary.

Vehicle is 2014 but tires are 2022

Minor scratch can be found all over body

Battery health is about 60% only

Rotors have minor rust due to idle, recommended skimming or replacement

**Engine Upper Cover**

Pass

**Engine Shield Cover**

Pass

**Engine Mounts**

Pass

**Engine Oil Condition**

Pass

**Engine Oil Leaks**

Pass

**Engine Oil Filler Cap**

Pass

**Coolant Level**

Pass

**Coolant Cap**

Pass

**Turbo / Supercharger**

Pass

**Visible Rust**

minor rust on rear brake rotors

**Exhaust System**

Pass

**Engine Idle**

Pass

**Bonnet Hinge & Holder**

Pass

**Fender Liners**

Pass

**Drive Belt / Pulleys**

Pass

**Hoses & Pipes**

Pass

**Radiator**

Pass

**Battery Condition** ⚡ ⚡ ⚡ ⚡ ⚡

### Fluid Level & Condition

Pass

### Transmission Fluid Leaks

Pass

### Gear Selector

Pass

### Gear Shifting

Pass

### Noise

Pass

Please review the car diagnostic report at the end of this document for more information on the transmission condition.

SAMPLE

**Key Remote**

Pass

**Entertainment System**

Pass

**Center Console Buttons**

Pass

**Door Lock / Unlock**

Pass

**Cameras**

Pass

**Cruise Control**

Pass

**A/C Control & Cooling**

Pass

**Starting & Ignition System**

Pass

**Gauges**

Pass

**Fog Lights**

Pass

**Headlights**

Pass

**Brake Lights**

Pass

**A/C Grilles**

Pass

**High Beams**

Pass

**Reverse Lights**

Pass

**Number Plate Lights**

Pass

**Indicators & Hazards**

Pass

**Soft Closing Doors**

Pass

**Wipers**

Pass

**Interior Lights**

Pass

**Sunroof / Moonroof**

Pass

**Windows Operation**

Pass

**Horn**

Pass

**Parking Sensors Fault**

Pass

**Seats Adjustment (Power/Manual)**

Pass

**Rear View / Side Mirror Electricals**

Pass

### Brake Pads Front

Pass

### Brake Pads Rear

Pass

### Brake Discs Front

Pass

### Brake Discs Rear

rotors have minor rust due to idle, recommended to skim or replace

### ABS Sensors

Pass

### Handbrake

Pass

### Front Suspension

Pass

### Rear Suspension

Pass

### Rims

	Brand	Condition
Front Left	Original	Good
Front Right	Original	Good
Rear Left	Original	Good
Rear Right	Original	Good

### Tyres

	Manufacturer	Date	Size	Condition
Front Left	Dunlop Grand Trek	2022	265/55/R20	6/7mm
Front Right	Dunlop Grand Trek	2022	265/55/R20	6/7mm
Rear Left	Dunlop Grand Trek	2022	265/55/R20	6/7mm
Rear Right	Dunlop Grand Trek	2022	265/55/R20	6/7mm

### Roof Lining

Pass

### Rear View Mirror

Pass

### Armrest & Side Pockets

Pass

### Steering Wheel Upholstery

Pass

### Seats Upholstery

Pass

### Gear Lever

Pass

### Floor Mats

Pass

### Trunk Lining

Pass

### Dashboard

Pass

### Front Windscreen

Pass

### Rear Windscreen

Pass

### Doors

Pass

### Service History

Available (ask seller to change ownership with agency for proof)




### User Manual

Available

## Service History & Manuals



# Paint Condition Report




## Key Details

- Scratch:** A minor or major scratch
- Paint Chip:** A small to medium part of the paint has been removed
- Dent:** A minor or major depression or hollow on the vehicle body
- Accident Paint:** Filler used to smoothen out the panel due to a deep crack or damage, followed by repainting of the panel.
- Cosmetic Paint:** No filler used, usually a repaint due to minor imperfections on the paint. e.g. stone chips, door dings, etc.
- Faded:** Paint and/or lacquer has been worn out due to extreme weather. Appears as a dull, washed out appearance and, at times discoloration.



## Chassis, Subframe & Internal Damage Report



Damage on Chassis / Subframe:

PASS

# General Exterior Photos



IMG\_20240515\_1132...  
652.08 KB



IMG\_20240515\_1132...  
563.34 KB



IMG\_20240515\_1132...  
614.64 KB



IMG\_20240515\_1132...  
566.5 KB



IMG\_20240515\_1132...  
628.19 KB



IMG\_20240515\_1133...  
637.97 KB



IMG\_20240515\_1133...  
584.9 KB



IMG\_20240515\_1133...  
640.13 KB



IMG\_20240515\_1133...  
680.35 KB



IMG\_20240515\_1133...  
620.18 KB



IMG\_20240515\_1133...  
632.34 KB



IMG\_20240515\_1133...  
666.75 KB



IMG\_20240515\_1133...  
598.04 KB



IMG\_20240515\_1134...  
610.64 KB



IMG\_20240515\_1134...  
624.72 KB



IMG\_20240515\_1136...  
627.96 KB



IMG\_20240515\_1136...  
598.33 KB



IMG\_20240515\_1136...  
699.98 KB

# Engine Bay & Undercarriage



IMG\_20240515\_1203...  
604.77 KB



IMG\_20240515\_1203...  
670.97 KB



IMG\_20240515\_1203...  
607.34 KB



IMG\_20240515\_1203...  
617.88 KB



IMG\_20240515\_1204...  
530 KB



IMG\_20240515\_1204...  
680.81 KB



IMG\_20240515\_1204...  
706.72 KB



IMG\_20240515\_1204...  
640.82 KB



IMG\_20240515\_1204...  
595.82 KB



IMG\_20240515\_1204...  
664.92 KB



IMG\_20240515\_1204...  
619.49 KB



IMG\_20240515\_1205...  
497.02 KB



IMG\_20240515\_1205...  
484.86 KB



IMG\_20240515\_1205...  
615.49 KB



IMG\_20240515\_1205...  
576.95 KB



IMG\_20240515\_1205...  
669.36 KB



IMG\_20240515\_1205...  
641.69 KB



IMG\_20240515\_1206...  
598.25 KB



IMG\_20240515\_1206...  
626.9 KB



IMG\_20240515\_1206...  
510.77 KB



IMG\_20240515\_1207...  
564.8 KB



IMG\_20240515\_1207...  
653.53 KB



IMG\_20240515\_1207...  
662.97 KB



IMG\_20240515\_1207...  
625.96 KB



IMG\_20240515\_1207...  
535.81 KB



IMG\_20240515\_1209...  
556.78 KB



IMG\_20240515\_1209...  
567.95 KB



IMG\_20240515\_1209...  
584.5 KB



IMG\_20240515\_1209...  
524.17 KB



IMG\_20240515\_1209...  
528.14 KB



IMG\_20240515\_1209...  
661.23 KB

# Interior Photos



IMG\_20240515\_1136...  
649.51 KB



IMG\_20240515\_1137...  
742.38 KB



IMG\_20240515\_1137...  
528.45 KB



IMG\_20240515\_1137...  
618.4 KB



IMG\_20240515\_1137...  
644.32 KB



IMG\_20240515\_1137...  
609.03 KB



IMG\_20240515\_1137...  
672.79 KB



IMG\_20240515\_1138...  
711.97 KB



IMG\_20240515\_1138...  
639.16 KB



IMG\_20240515\_1138...  
590.38 KB



IMG\_20240515\_1139...  
641.89 KB



IMG\_20240515\_1140...  
648.93 KB



IMG\_20240515\_1140...  
623.26 KB



IMG\_20240515\_1140...  
722.08 KB



IMG\_20240515\_1140...  
687.14 KB

SAMPLE

# Vehicle Diagnostic Report

PDF

Toyota(DTC)\_98935000676...pdf

**WE JUST OUTPERFORMED YOUR INSURANCE BROKER**

We've built the insurance experience from the ground up!

- Get Car Insurance Without Talking To A Human - For The First Time Ever!
- Lowest quotes, transparent pricing, instant cover available 24/7. Policy issued to RTA in 3 minutes.

**TRY THE MAGIC**

## Terms of Service

All services from BeSoji are provided on an "as is, with all defects" and "as available" basis without warranties of any kind, either expressed or implied, including without limitation, warranties of title, non-infringement, or implied warranties of merchantability or fitness for a particular purpose. Nothing in these terms or in any description of products or services in the services shall constitute a representation or warranty with respect to such products or services.

The inspection of the vehicle described in this report is external and we are unable to accept responsibility for failure to identify defects not present or apparent at the time of the inspection. Odometer readings may have been tampered with, although we report any signs that we notice of this happening during inspection. You acknowledge, by your use of the services, that such use is at your sole risk. In the event of dissatisfaction or a complaint, we reserve the right to re-examine the vehicle prior to any rectifications to the vehicle. You agree that BeSoji's liability is limited to refunding the price you pay for the inspection in the event you are dissatisfied with BeSoji's service, or injuries occur due to an unreported defect in the vehicle. All requests should be sent to hello@besoji.com within 7 days notice of receiving the report.

in no event shall either BeSoji or its affiliates or agents be liable for any direct, indirect, punitive, incidental, special or consequential damages arising out of or in any way connected with the use of the services, whether based on contract, tort, strict liability or otherwise, even if advised of the possibility of any such damages.